
CONTROL FOR COOLING FAN 2/23/04
Harold Bettencourt, Jr. et al.


Greer, Burns & Crain, Ltd. (Lawrence J. Crain)
Ref. No. 0349.69065 (312) 360-0080
Sheet 1 of 13







CONTROL FOR COOLING FAN 2/23/04
Harold Bettencourt, Jr. et al.
Greer, Burns & Crain, Ltd. (Lawrence J. Crain)
Ref. No. 0349.69065 (312) 360-0080
Sheet 2 of 13









CONTROL FOR COOLING FAN 2/23/04
Harold Bettencourt, Jr. et al.
Greer, Burns & Crain, Ltd. (Lawrence J. Crain)
Ref. No. 0349.69065 (312) 360-0080
Sheet 4 of 13






FIG. 5

CONTROL FOR COOLING FAN 2/23/04
Harold Bettencourt, Jr. et al.
Greer, Burns & Crain, Ltd. (Lawrence J. Crain)
Ref. No. 0349.69065 (312) 360-0080
Sheet 5 of 13







FIG. 6

CONTROL FOR COOLING FAN 2/23/04
Harold Bettencourt, Jr. et al.
Greer, Burns & Crain, Ltd. (Lawrence J. Crain)
Ref. No. 0349.69065 (312) 360-0080
Sheet 6 of 13





CONTROL FOR COOLING FAN 2/23/04
Harold Bettencourt, Jr. et al.
Greer, Burns & Crain, Ltd. (Lawrence J. Crain)
Ref. No. 0349.69065 (312) 360-0080
Sheet 7 of 13








FIG. 8

CONTROL FOR COOLING FAN 2/23/04


Harold Bettencourt, Jr. et al.


Greer, Burns & Crain, Ltd. (Lawrence J. Crain)

Ref. No. 0349.69065 (312) 360-0080

Sheet 8 of 13













FIG. 11








FIG. 13






FIG. 14






FIG. 15A





FIG. 15B








FIG. 16B

